

RECEIVING INSPECTION REPORT

HYCON MFG. COMPANY

No. 127787

Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080083-2

RECEIVED FROM

DATE REC'D

P. O. NO.

12/20/56

VENDOR PACKING SLIP NO.

1147

CHARGE TO
QUANTITY
RECEIVEDCONTRACT
CODE NO.DRAWING
NUMBERDWG. DASH OR
STANDARD PART NO.DWG.
REV.LOT
NO.CLASS
NUMBEROPER.
NUMBERBUY OUT
CODE NO.

O

ACCT. OR

W. O. NO.

S. O. NO.

DRAWING NO. AND DESCRIPTION

ACCEPTED

REJECTED

REMARKS

730163-18 RELAY

200

RECEIVED
BYINSPECTED
BY

DATE

12/26/56

REJECTS RETURNED
ON SHIP. MEMO NO.

COPY

RECEIVING INSPECTION REPORT

HYCON MFG. COMPANY

2961 E. COLORADO ST., PASADENA 8, CALIF

No. 127806

RECEIVED FROM

Elgin National Watch Co.

DATE REC'D

12/26/56

P. O. NO.

69086

VENDOR PACKING SLIP NO.

CHARGE TO
QUANTITY
RECEIVEDCONTRACT
CODE NO.DRAWING
NUMBERDWG. DASH OR
STANDARD PART NO.DWG.
REV.LOT
NO.CLASS
NUMBEROPER.
NUMBERBUY OUT
CODE NO.

O

ACCT. OR

W. O. NO.

S. O. NO.

DRAWING NO. AND DESCRIPTION

QUANTITY

ACCEPTED

REJECTED

REMARKS

5

730125-10 Relays

P. O. 69086

Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080083-2

RECEIVED
BY

Ken Hite

INSPECTED
BY

DWA

DATE

12/26/56

REJECTS RETURNED